



Department of Veterans Affairs

Federal Supply Schedule Service
Authorized Federal Supply Schedule Price List
Cumulative Price List
Effective May 16, 2010

On-line access to contract ordering information, terms and conditions, up-to-date pricing, and the option to create an electronic delivery order are available through GSA *Advantage!* a menu-driven database system. The INTERNET address for GSA *Advantage!* is: GSAAdvantage.gov

Medical Equipment and Supplies FSC Group 65, Part II Sections A FSC Class 6530

Contract No: V797P-4809a Contract Period: May 16, 2010 through May 15, 2015

For more information on ordering from Federal Supply Schedules click on the FSS Schedules button at fss.gsa.gov

Surgical Repairs International (SRI) 70 Pearce Avenue Tonawanda, NY 14150

> Phone: 1-800-724-9885 Fax: 716-873-1609 www.srirepairs.com

Size of Business: Small

TIN: 16-1413258

CUSTOMER INFORMATION

1. Table awarded special item number(s) with appropriate cross-reference to page number(s):

SIN(s) FSS Page Location Basic Discount
A-200 7-13 Minor repairs 15%
Major repairs 15%

2. Maximum order: \$500,000.00 (A-200)

3. Minimum order: None

- 4. Geographic coverage: 50 States, Washington D.C., and Puerto Rico
- 5. Point(s) of production: Not Applicable
- 6. Discount: Prices shown herein are net, discount deducted.
- 7. Quantity Discounts: 2% off invoice for repair orders in excess of \$5,000.00 2% additional discount for VSN's using SRI exclusively
- 8. Prompt payment terms: Net 30 days
- 9a. Government commercial credit cards are accepted with no additional discounts.
- 9b. Government commercial credit cards are accepted up to and above the \$2,500.00 micro-purchase threshold.
- 10. Time of delivery:

Flexible endoscopes: Minor repairs within 2 days after receipt of approval

Major repairs within 5 days after receipt of approval

Rigid endoscopes: Within 4 days after receipt of approval Within 5 days after receipt of approval Power equipment: Dental Hand pieces: Within 5 days after receipt of approval Phaco Hand pieces: Within 3 days after receipt of approval Fiber Optic Light Cords: Within 7 days after receipt of approval Video Equipment: Within 5 days after receipt of approval Within 4 days after receipt of approval Surgical Instruments: Flexible Biopsy Forceps: Within 7 days after receipt of approval

- 11a. Accelerated delivery: All items above reduced by (1) day for rush requests. Government is responsible for paying the difference between normal and expedited freight charges.
- 11b. Overnight and 2-day delivery service are available for all items listed above. Please contact Surgical Repairs International for rates.
- 12. F.O.B. point(s): F.O.B. Destination 50 States, Washington D.C., and Puerto Rico
- 13a. Ordering address(es): Surgical Repairs International (SRI), 70 Pearce Avenue, Tonawanda, NY 14150, Telephone Number: 1-800-724-9885
- 13b. Ordering procedures: For supplies and services, the ordering procedures, information on Blanket Purchase Agreements (BPA's), and a sample BPA can be found at the GSA/FSS Schedule homepage (fss.gsa.gov/schedules).
- Payment address: Surgical Repairs International (SRI), 70 Pearce Avenue,
 Tonawanda, NY 14150

CUSTOMER INFORMATION CONTINUED

15. Warranty: Surgical Repairs International (SRI) warranty covers defects in materials and workmanship (under normal use) after date of delivery for the periods listed below. Our warranty does not cover damage resulting from accidents, misuse, mishandling or negligence. SRI is responsible for shipping charges.

| <u>Product</u> | Warranty Period |
|-------------------------|------------------------|
| Flexible Endoscopes | 120 days |
| Rigid Endoscopes | 120 days |
| Power Equipment | 120 days |
| Phaco Hand pieces | 120 days |
| Dental hand pieces | 120 days |
| Video Equipment | 120 days |
| Surgical Instruments | 120 days |
| Fiber Optic Light Cords | 120 days |
| Flexible Biopsy Forceps | 120 days |

SRI will inspect newly-purchased instruments/equipment at no charge and will provide you with an estimate for the repair. Any damage that is found to be covered under your original manufacturer's warranty will be immediately reported to you and the instrument will be returned. Once in SRI possession, each item is insured for its full replacement value.

- 16. Return Goods Policy: Ground-shipping charges incurred for returning equipment under warranty will be paid by SRI. SRI will pay for freight in the event of a shipping error caused by SRI. If the shipping error is a result of the ordering facility, freight will be paid by them.
- 17. Loaner Equipment: SRI provides loaner equipment to its customers while their instrument is being repaired. The customer maintains full responsibility while the loaner instrument is in their possession. If the loaner is damaged, SRI will bill the facility for the amount of the repair or the full value of the instrument, whichever is less.
 - (a) Loaners must be returned to SRI within five (5) days after receipt of the repaired instrument.
 - (b) Customers are responsible for handling and shipping charges.
 - (c) Loaners can be requested by calling 1 (800) 724-9885.
- 18. In-services/Preventative maintenance (personnel training):

FREE IN-SERVICE TRAINING (FLEXIBLE & RIGID ENDOSCOPES)

This training is designed for: Biomedical Engineering, GI/Endoscopy, SPD and OR staff SRI strongly recommends the implementation of in-services in order to help minimize unnecessary expenditures and regular equipment breakdown. This service is provided free of charge and at the customer's request. In-services are administered by SRI personnel with extensive experience in product knowledge and maintenance. This program will give a better appreciation of the value and sensitive nature of the endoscopes and should instill a greater desire to protect them. This highly advanced and practical training offers the following:

CUSTOMER INFORMATION CONTINUED

- > A demonstration and explanation of the endoscope's operating functions
- > A Close look at the internal components
- > Most common repairs and their causes
- Proper care, handling and reprocessing techniques
- > Proper leak testing procedures
- > Troubleshooting tips

Customers are also welcome to visit our repair facility to gain a visual understanding of the repair processes and become acquainted with our technical staff.

FREE PREVENTATIVE MAINTENANCE & ON-SITE INSPECTION (FLEXIBLE & RIGID ENDOSCOPES)

SRI strongly recommends the implementation of routine on-site inspection and evaluation of flexible and rigid endoscopes to promptly identify and correct minor problems before they become more costly. This service is provided free of charge and at the customer's request. This program will help you have an ongoing awareness of the condition of your equipment and allow you to better control your expenditures by taking a proactive role in monitoring your inventory. This service offers the following:

- Thorough on-site inspection and evaluation of endoscopes
- > Evaluation of cleaning and storage conditions
- > Identifies endoscopes needing immediate attention to avoid increased damage
- > Provides preventative maintenance tips to help minimize costly repairs
- Provides detailed computerized evaluation reports
- 19. Data Universal System (DUNS) number: 786789206
- 20. Notification regarding registration in Central Contractor Registration (CCR) database: YES

PRICE LIST

| Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|----------------------------------------------|
| FLE | XIBLE ENDOSCOPE REPAIRS | | |
| Eyepie | ce / Switch Block Repairs | | |
| FE01 FE02 FE03 FE04 FE05 FE06 FE07 FE08 FE09 FE10 | Rebuild eyepiece Repair button Replace #1 button Rebuild switch block Replace switch block (100 and 140 series) Replace switch block (160 series) Repair leaking eyepiece / switch block Replace eyepiece cover / housing Remask image guide Polish eyepiece window | \$250.00 \$60.00 \$110.00 \$250.00 \$260.00 \$295.00 \$75.00 \$250.00 \$250.00 | Each Each Each Each Each Each Each Each |
| FE11 FE12 | Replace eyepiece window Replace Pentax button / switch assembly | \$120.00 \$75.00 | Each Each |
| | I Body Repairs | ψ. σ.σσ | 20011 |
| FE14 FE15 FE16 FE17 FE18 | Reseal control body Repair / reseal suction chamber Repair auxiliary water leak Replace suction chamber Replace auxiliary water housing | \$75.00 \$230.00 \$75.00 \$850.00 \$350.00 | Each Each Each Each Each |
| Insertic | on Tube Repairs | | |
| FE19 FE20 FE21 FE22 FE24 FE25 | Repair bite/ dent in insertion tube Repair cut or hole in insertion tube Install boot extender Replace insertion tube Replace insertion tube boot Adjust insertion tube stiffener (Olympus 160 series) | \$75.00 \$75.00 \$180.00 \$2,500.00 \$290.00 \$150.00 | Each Each Each Each Each Each |
| Bendin | g Section Repairs | | |
| FE26 FE27 FE28 FE29 | Replace bending rubber Repair bite/dent in bending section assembly Replace bending section wire mesh Replace bending section | \$120.00 \$150.00 \$450.00 \$950.00 | Each Each Each Each |
| Angula | tion Repairs | | |
| FE30 FE31 FE32 FE33 FE34 FE35 FE36 FE37 FE38 FE39 | Minor angulation adjustment Full angulation adjustment Replace angulation wire Each additional angulation wire Adjust Elevator wire Replace elevator wire Repair knob lock Rebuild knob assembly Rebuild knob assembly (Olympus 140 series) Replace angulation knob shaft | \$150.00 \$180.00 \$490.00 \$200.00 \$150.00 \$450.00 \$150.00 \$250.00 \$850.00 | Each Each Each Each Each Each Each Each |

| Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|-------------------|----------------------------------------------------------------------------------|-----------------------------------------|---------------------------|
| FE40 | Repair / Replace angulation wire coil pipe | \$365.00 | Each |
| FE41 | Replace angulation wires and coil pipes (x4) | \$1,400.00 | Each |
| FE42 | Replace coil pipe holder | \$150.00 | Each |
| FE43 | Refurbish angulation system | \$800.00 | Each |
| FE44 | Replace right/left knob lock – Pentax | \$250.00 | Each |
| FE45 | Replace drum cables (pair) – Pentax | \$300.00 | Each |
| FE46 | Lubricate angulation system (bronchoscopes, cystoscopes, intubation scopes only) | \$200.00 | Each |
| Air / Wa | ter Repairs | | |
| FE47 | Replace air / water o-rings | \$30.00 | Each |
| FE48 | Unclog air / water channel | No charge | Each |
| FE49 | Replace nozzle | \$35.00 | Each |
| FE50 | Repair auxiliary water leak | \$60.00 | Each |
| Channe | I Repairs | · | |
| FE51 | Replace biopsy channel | \$850.00 | Each |
| FE52 | Replace biopsy channel – Bronchoscope | \$1,195.00 | Each |
| FE53 | Replace suction channel | \$395.00 | Each |
| FE54 | Repair elevator channel | \$1,200.00 | Each |
| FE55 | Unclog suction channel | \$250.00 | Each |
| FE56 | Replace water channel in light guide tube | \$395.00 | Each |
| FE57 | Replace water channel in insertion tube | \$995.00 | Each |
| Tip Rep | · | *************************************** | |
| FE58 | Replace light guide lens (each) | \$100.00 | Each |
| FE59 | Replace light guide assembly | \$250.00 | Each |
| FE60 | Reseal lens | \$60.00 | Each |
| FE61 | Replace C-cover - Olympus | \$180.00 | Each |
| FE62 | Replace C-cover - Pentax | \$450.00 | Each |
| FE63 | Polish lens | \$60.00 | Each |
| FE64 | Reseal objective lens assembly | \$350.00 | Each |
| FE65 | Repair objective lens assembly | \$750.00 | Each |
| FE66 | Rebuild / replace objective lens assembly | \$1,500.00 | Each |
| | uide Tube/Universal Cord Repairs | ψ.,σσσ.σσ | 200 |
| FE67 | Repair dent | \$75.00 | Each |
| FE68 | Repair cut or hole | \$75.00 \$75.00 | Each |
| FE69 | Replace light guide bundle | \$980.00 | Each |
| FE70 | | \$980.00 | Each |
| | Replace light guide tube uide Connector / Video Connector Repairs | φ960.00 | EdCII |
| | • | A1 1 | |
| FE71 | Reseal light guide prong | No charge | Each |
| FE72 | Repair / replace light guide prong cover – Cystoscope, Bronchoscope | \$250.00 | Each |
| FE73 | Reseal light guide housing | \$60.00 | Each |
| FE74 | Replace light guide prong window | \$130.00 | Each |
| FE75 | Tighten connector | \$60.00 | Each |
| FE76 | Repair ETO valve | \$60.00 | Each |
| FE77 | Remove residue from light guide prong | \$60.00 | Each |

| Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|-------------------|----------------------------------------------------------------------------------------------------------------------------------|------------------|---------------------------|
| FE78 | Replace light guide handle (URF, CYF, etc.) | \$550.00 | Each |
| FE79 | Repair CO2 or water connector (water bottle) | \$120.00 | Each |
| FE80 | Replace light guide prong tip | \$75.00 | Each |
| FE81 | Replace light guide prong tip and window | \$220.00 | Each |
| Fluid In | vasion | | |
| FE82 | Remove major fluid invasion | \$490.00 | Each |
| FE83 | Remove minor fluid invasion | \$290.00 | Each |
| FE84 | Aerate scope | \$150.00 | Each |
| Miscella | aneous Repairs | | |
| FE85 | Repair CCD chip / wiring | \$1,200.00 | Each |
| FE86 | Repair CCD chip / wiring on Olympus 160-series | \$1,950.00 | Each |
| FE87 | Refurbish video connector / replace RF pins (Olympus) | \$540.00 | Each |
| FE88 | Refurbish video connector / replace RF pins on Olympus 160-series | \$800.00 | Each |
| FE89 | Replace field lens on image guide – Cystoscope, Bronchoscope | \$1,500.00 | Each |
| FE90 | Replace image guide – Cystoscope | \$1,800.00 | Each |
| FE91 | Replace image guide – Bronchoscope | \$2,950.00 | Each |
| FE92 | Video overhaul repair (replace insertion tube and light guide tube) | \$3,200.00 | Each |
| FE93 | Bronchoscope overhaul repair (replace insertion tube, image guide, light guide bundle if needed, and light guide tube if needed) | \$3,950.00 | Each |
| FE94 | Remove image stain (fiberoptic scopes only) | \$800.00 | Each |
| FE95 | High-level disinfection (for leaking scope) | \$150.00 | Each |

RIGID ENDOSCOPE REPAIRS (DOES NOT INCLUDE SPECIALTY SCOPES)

Level Pricing Option:

| RE01 | Diamond polishing | No Charge | Each |
|------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|------|
| RE02 | Level I Thorough diagnostic testing & cleaning of scope Comprehensive leakage and shock test Diamond polishing of sapphire window or tip lens Fiberoptic light connection rebonding & polishing Opening & testing of interior optical system, including ocular lens Functional testing of all mechanical parts Laser adjustment of optical system & ocular lens Complete disassembly & cleaning of entire optical lens system Hermetic sealing of endoscope | \$290.00 | Each |
| RE03 | Level I plus: | \$ 490.00 | Each |

Replace/repair complete objective lens system


Recalibrate optical lens spacers


| Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|----------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------|----------------------------------------------|
| RE04 | Level III Level II plus: Replace inner and outer tubing Replace fiberoptic light bundle Additional Parts | \$ 690.00 | Each |
| REP01 REP02 REP03 REP04 REP05 REP06 | Eyepiece Negative lens Rod lens Light crystal Ocular lens Window | \$90.00 \$65.00 \$65.00 \$68.00 \$75.00 \$58.00 | Each Each Each Each Each Each |
| DEOF | Flat Rate Option: | \$500.00 | Fach |
| RE05 | Levels I, II, or III | \$590.00 | Each |
| | ER EQUIPMENT REPAIRS | | |
| PPH01 | Level I Initial test and analysis Disassemble & clean Replace all seals & o-rings, lubricate system Performance test & calibrate to manufacturer's specifications | \$ 150.00 | Each |
| PPH02 | Level II Level I plus: Remove oxidation Replace all worn or missing bearings, springs, retaining rings, & clips | \$240.00-\$340.00 | Each |
| PPH03 | Level III Level I & II plus: Remove oxidation Repair/replace as required: Gear box, drive/ output shaft, distributor, control mechanism, swivel mechanism, and/or collet mechanism | \$450.00-\$550.00 | Each |
| _ | & Electrical Handpieces: Level I Replace all worn or missing o-rings & seals Clean & lubricate system Performance test & calibrate to manufacturer's specifications | \$ 300.00-\$450.00 | Each |
| PEBH02 | Level II Level I plus: Refurbish/replace motor or board components, cable connectors Replace up to 2 bearings/gears, all o-rings, all seals | \$450.00-\$590.00 | Each |

| Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------|---------------------------|
| PEBH03 | Level III Level I & II plus: Repair/replace motor Replace all worn or missing bearings, gears, o-rings, & seals Orthopedic Air Hoses | \$590.00-\$990.00 | Each |
| PAH01 | Level I Intermediate repair | \$86.00 | Each |
| PAH02 | Level II Complete overhaul | \$ 115.00 | Each |
| PB01 PC01 | Miscellaneous Battery Refurbishment (new cells) Cable Replacement (for Dyonics, Linvatec & Stryker cords) | \$120.00-\$140.00 \$450.00 | Each Each |
| PHA PH01 | General repairs Overhaul includes: a. State of the art analysis of your handpiece (measures all critical functions and detects even minute amounts of moisture) b. Replace all crystals c. Replace phaco tip d. Repair leaks in irrigation line e. Replace cable f. Replace connector g. Refurbish exterior case h. Calibrate entire system i. Pressure, shock, and seal test | \$200.00-\$1,150.00 | Each |
| DH01 DH02 DH03 | TAL HANDPIECE REPAIRS Overhaul – Flat rate (1-9) Overhaul – Flat rate (10+) Fiberoptic replacement for high speed handpieces EO EQUIPMENT REPAIRS | \$95.00 \$85.00 \$175.00-\$230.00 | Each Each Each |
| | Endoscopic Video Cameras Single chip cameras | | |
| VC01 VC02 | Single end cable repair Cable replacement: Older models (Storz 9050B, | \$895.00 \$895.00 | Each Each |
| VC03 | Olympus OTV-S2, Stryker 590, 592, and 596, etc.) Cable replacement: Storz Telecam series, Olympus OTV-S4 & OTV-S5, Linvatec 8160, 8171, & 8172; Circon/ACMI MV-9690 & 9692, Wolf cameras | \$1,195.00 | Each |
| VC04 | with edge card connector Cable replacement: Dyonics D1, Circon/ACMI MV-10000 | \$1,495.00 | Each |

| VP02 Mechanical problems (parts extra) \$390.00 Each VP03 Horizontal line on print out \$690.00 Each SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|---------------------------|
| VC07 Cable replacement: Stryker 777, 780, 782, 810, & 850, 888; Dyonics D3; K. Storz Tricam; Olympus OTV-SX; Circon/ACMI MV-9906; Linvatec 9010; R. Wolf 5504 VC08 Cable replacement: Dyonics D3E & ED3 \$1,695.00 Each VC09 IR filter replacement: Dyonics D3E & ED3 \$895.00 Each Endoscopic Video Couplers, Zoom Couplers and Beam Splitters: VCB01 Most couplers: Repair fluid invasion, replace all broken seals \$325.00 Each VCB02 Stryker & Dyonics couplers: Repair broken scope mounts \$595.00 Each VCB03 Zoom couplers: Repair fluid invasion, replace all broken seals \$4495.00 Each VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals \$4450.00 Each VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals \$450.00 Each VCB04 Mechanical problems (parts extra) \$390.00 Each VP02 Mechanical problems (parts extra) \$390.00 Each VP03 Horizontal line on print out \$690.00 Each SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | | Three-chip cameras | | |
| VC09 IR filter replacement: Dyonics D3E & ED3 Endoscopic Video Couplers, Zoom Couplers and Beam Splitters: VCB01 Most couplers: Repair fluid invasion, replace all broken seals VCB02 Stryker & Dyonics couplers: Repair broken scope mounts VCB03 Zoom couplers: Repair fluid invasion, replace all broken seals VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals VCB05 VCB06 VCB06 Printers: VP01 Clean and re-calibrate, switch repair/replacement VP02 Mechanical problems (parts extra) VP03 Horizontal line on print out SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | | Cable replacement: Stryker 777, 780, 782, 810, & 850, 888; Dyonics D3; K. Storz Tricam; Olympus OTV-SX; Circon/ACMI MV-9906; Linvatec 9010; R. Wolf 5504 | | |
| Endoscopic Video Couplers, Zoom Couplers and Beam Splitters: VCB01 Most couplers: Repair fluid invasion, replace all broken seals \$325.00 Each VCB02 Stryker & Dyonics couplers: Repair broken scope mounts \$595.00 Each VCB03 Zoom couplers: Repair fluid invasion, replace all broken seals \$495.00 Each VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals \$450.00 Each Endoscopic Video Printers: VP01 Clean and re-calibrate, switch repair/replacement \$290.00 Each VP02 Mechanical problems (parts extra) \$390.00 Each VP03 Horizontal line on print out \$690.00 Each SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | | · | • | |
| VCB01 Most couplers: Repair fluid invasion, replace all broken seals VCB02 Stryker & Dyonics couplers: Repair broken scope mounts VCB03 Zoom couplers: Repair fluid invasion, replace all broken seals VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals VCB04 Endoscopic Video Printers: VP01 Clean and re-calibrate, switch repair/replacement VP02 Mechanical problems (parts extra) VP03 Horizontal line on print out SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | | • | ******** | |
| VCB03 Zoom couplers: Repair fluid invasion, replace all broken seals VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals Endoscopic Video Printers: VP01 Clean and re-calibrate, switch repair/replacement VP02 Mechanical problems (parts extra) VP03 Horizontal line on print out SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | VCB01 | Most couplers: Repair fluid invasion, replace all broken seals | \$325.00 | Each |
| VCB04 Beamsplitters: Repair fluid invasion, replace all broken seals Endoscopic Video Printers: VP01 Clean and re-calibrate, switch repair/replacement VP02 Mechanical problems (parts extra) VP03 Horizontal line on print out SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | VCB02 | · · · · · · · · · · · · · · · · · · · | \$595.00 | Each |
| Endoscopic Video Printers: VP01 Clean and re-calibrate, switch repair/replacement \$290.00 Each VP02 Mechanical problems (parts extra) \$390.00 Each VP03 Horizontal line on print out \$690.00 Each SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | | | • | |
| VP01 Clean and re-calibrate, switch repair/replacement VP02 Mechanical problems (parts extra) VP03 Horizontal line on print out SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments \$290.00 Each \$390.00 Each \$690.00 | VCB04 | Beamsplitters: Repair fluid invasion, replace all broken seals | \$450.00 | Each |
| VP02 Mechanical problems (parts extra) \$390.00 Each VP03 Horizontal line on print out \$690.00 Each SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | | Endoscopic Video Printers: | | |
| VP03 Horizontal line on print out \$690.00 Each SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | VP01 | Clean and re-calibrate, switch repair/replacement | \$290.00 | Each |
| SURGICAL INSTRUMENT REPAIRS Laparoscopic Instruments | VP02 | Mechanical problems (parts extra) | \$390.00 | Each |
| Laparoscopic Instruments | VP03 | Horizontal line on print out | \$690.00 | Each |
| | SUR | GICAL INSTRUMENT REPAIRS | | |
| LID1 Lan edissors inserts - Microscopic sharpening & cleaning \$ \$25.00 Each | | Laparoscopic Instruments | | |
| LIU I LAP SUISSUIS INSCIES — MICHOSCOPIC SHALPEHING & CICANNING \$723.00 EACH | LI01 | Lap scissors inserts – Microscopic sharpening & cleaning | \$25.00 | Each |
| LI02 Laparoscopic scissors- Microscopic sharpening & cleaning \$46.00 Each | LI02 | | \$46.00 | Each |
| LI03 Screw replacement \$35.00 Each | LI03 | Screw replacement | \$35.00 | Each |
| LI04 Tube insulation \$58.00 Each | LI04 | Tube insulation | \$58.00 | Each |
| LI05 General repair (includes tube insulation) \$95.00 Each | | , , | • | |
| LI06 General repair with reinsulated handle \$130.00 Each | LI06 | General repair with reinsulated handle | \$130.00 | Each |
| Ophthalmic/Micro Instruments | | Ophthalmic/Micro Instruments | | |
| MI01 Needle holder - Align & refurbish \$29.00 Each | MI01 | Needle holder - Align & refurbish | \$29.00 | Each |
| MI02 Replace tungsten inserts \$68.00 Each | MI02 | Replace tungsten inserts | \$68.00 | Each |
| MI03 Intraocular scissors & forceps \$68.00 Each | | Intraocular scissors & forceps | • | Each |
| MI04 Eye spring scissors \$22.00 Each | | | | Each |
| MI05 Iris / tenotomy scissors \$5.90 Each | | | · | |
| MI06 Alligator forceps \$36.00 Each | | · · | • | |
| MI07 Thumb forceps \$28.00 Each | | • | • | |
| MI08 Thumb forceps with teeth - Set & clean \$33.00 Each | | · | | |
| MI09 Eye forceps - Align & clean \$34.00 Each | | | | |
| MI10 Eye forceps - Replace teeth \$66.00 Each MI11 R.K. forceps \$77.00 Each | | | • | |
| MI11 R.K. forceps \$77.00 Each MI12 Eye pick & probe \$31.00 Each | | · | ' | |
| MI13 Ophthalmic retractors \$23.00 Each | | · · · · · | | |
| MI14 Microscopic sharpening trephines \$15.50 Each | | · | | |
| MI15 Spuds, spatulas, & loops - General microscopic repair \$11.20 Each | | | | |
| MI16 Eye hook – Skin hook \$31.00 Each | | | | |
| MI17 Eye knives – Microscopic sharpening / repair \$12.00 Each | | · · | | |
| MI18 Blade brakers \$29.00 Each | | · · · · · · · · · · · · · · · · · · · | | |
| MI18 Cystotome – cannula \$14.00 Each | MI18 | Cystotome – cannula | | |
| MI19 Dilator \$5.90 Each | MI19 | Dilator | \$5.90 | Each |

| Catalog Number | Product Description | FSS Net Price | Package Size Priced |
|-------------------|--------------------------------------------------------------------------------------------|----------------------|---------------------------|
| MI20 | Eye calipers | \$30.00 | Each |
| MI21 | Kelly punch | \$37.20 | Each |
| MI22 | Eye marker | \$32.00 | Each |
| MI23 | Beaver handle | \$5.90 | Each |
| | Orthopedic Instruments | | |
| OI01 | Arthroscopic scissors, punches, forceps, shavers – Repair, microscopic sharpen & refurbish | \$36.00 | Each |
| OI02 | Arthroscopic intra-articular hooks, knives - Repair, micro sharpen & refurbish | \$25.00 | Each |
| OI03 | Ronguers, bone cutters | \$28.00 | Each |
| OI04 | Pin cutters | \$39.00 | Each |
| OI05 | Chisels, osteotomes, curettes, elevators & gouges | \$5.90 | Each |
| OI06 | Reamers | \$22.00 | Each |
| OI07 | Mallet repair | \$13.00 | Each |
| O108 | Drill bits | \$9.00 | Each |
| | General Instruments | | |
| GI01 | Stainless steel scissors – Microscopic sharpening & refurbishing | \$5.90 | Each |
| GI02 | Vascular, delicate, angled, circumflex scissors - Microscopic sharpening & refurbishing | \$7.50 | Each |
| GI03 | Tungsten scissors – Microscopic sharpening & refurbishing | \$9.00 | Each |
| GI04 | Forcep – Clean, align, & refurbish | \$5.90 | Each |
| GI05 | Needle holder, stainless steel - Clean, align, & refurbish | \$5.90 | Each |
| GI06 | Needle holder, tungsten - Replace tungsten inserts | \$30.00 | Each |
| GI07 | Needle holder – Convert stainless steel to tungsten | \$36.00 | Each |
| GI08 | Abdominal / chest retractor | \$9.00 | Each |
| GI09 | Self-retaining retractor | \$5.90 \$5.00 | Each |
| GI10 | Hand retractor | \$5.90 | Each |
| GI11 | Nasal speculum | \$13.00 | Each |
| GI12 GI13 | Vaginal speculum | \$13.00 \$5.90 | Each |
| GI13 GI14 | Mouth gag Verres / biopsy needle | \$5.90 \$5.90 | Each Each |
| GI14 GI15 | Dilators & sounds | \$5.90 \$5.90 | Each |
| GI16 | Suction tubes | \$5.90 | Each |
| GI17 | Instrument racks | \$5.90 | Each |
| GI18 | Refurbish tray | \$50.00 | Each |
| | • | 7 -3-1-3-3 | |
| | EROPTIC LIGHT CORD REPAIRS | *** | |
| FLC01 | Refiber only, 6' – 7' length | \$98.00 | Each |
| FLC02 | Replace sheath, 6' – 7' length | \$120.00 | Each |
| FLC03 FLC04 | Replace one or both ends | \$135.00 \$360.00 | Each Each |
| | Liquid light cables | \$300.00 | Each |
| FLE | XIBLE BIOPSY FORCEP REPAIRS | | |
| FBF01 | Standard | \$140.00 | Each |
| FBF02 | Hot | \$160.00 | Each |
| _ | | | |







70 Pearce Avenue • Tonawanda, NY 14150 • USA (800) 724-9885 • Phone: (716) 873-3229 • Fax: (716) 873-1609 www.srirepairs.com